

# Product Change Notification (PCN): 0023 Colibri T30 1GB V1.1G and 0030 Colibri T30 1GB IT V1.1B to versions V1.1X

Date of publication: 25 Apr 2023

## Table of Contents

- 1. Affected Products
- 2. Product Phase-in / Phase-out Schedule
- 3. Description of Changes
  - Change #1: Removal of level shifter
- 4. Customer Impact
  - Hardware
  - Software
    - Customer Software
    - Toradex Linux BSP
    - Windows CE
- 5. Contact

## 1. Affected Products

End of Life Product		Additional Substitution Version (with limited features to increase availability, group EOL still apply)	
Part Number	Product Name	Part Number	Product Name
00231106	Colibri T30 1GB V1.1G	00231123	Colibri T30 1GB V1.1X
00301101	Colibri T30 1GB IT V1.1B	00301123	Colibri T30 1GB IT V1.1X

## 2. Product Phase-in / Phase-out Schedule

End of Life Product		Additional Substitution Version (with limited features to increase availability, group EOL still apply)	
Part Number	Estimated Schedule	Part Number	Estimated Schedule
00231106	Last time buy (LTB)/Last time ship (LTS) can not be assured due to overwhelming LTB for EOL of product group and complex supply situation. In order to keep validation effort for our customers to a minimum, we are introducing a new version with one single functional change.	00231123	Sample: April, 2023
00301101		00301123	Volume: June 2023  LTB (Last Time Buy): 2023-06-15 non-cancellable and non-returnable, subject to availability of key components LTS (Last Time Ship): 2025-01-15

Customers not requiring the parallel camera input are strongly encouraged to use the additional substitution version. Toradex also advises customers to validate the new product version before their production release, we can provide a rework instruction or “Sample” of the additional substitution version.

### 3. Description of Changes

---


#### **Change #1: Removal of level shifter**

- Removed TI 74AVCA164245ZQLR and related components due to component EOL and shortage

## 4. Customer Impact

### Hardware

- Parallel camera interface won't be available in V1.1X
- No changes are required on the Colibri carrier board
- SoM Pins affected by this change are : 59, 65, 67, 69, 71, 77, 79, 81, 85, 94, 96, 97, 98, 101, 103  
(see Table 5-18 - Camera Interface Pins in [Colibri T30 datasheet](#))
- All the affected SoM pins multiplexed. They are connected to 2 pins on the SoC-side  
(see Table 4-1 - Colibri Multiplexed Pins in [Colibri T30 datasheet](#))



### Affected Pins on SODIMM Connector X1

X1 Pin#	Tegra Pin 1	Tegra pin 2
59	SDMMC3_DAT3	VI_D7
65	PEX_L1_CLKREQ_N	VI_D9
67	SDMMC3_CMD	VI_D6
69	PEX_L1_RST_N	VI_D10
71	GPIO_PV2	VI_D0
77	GPIO_PCC2	VI_D11
79	SDMMC1_DAT2	VI_D4
81	LCD_PWR1	VI_VSYNC
85	GPIO_PV3	VI_D8
94	PEX_L2_CLKREQ_N	VI_HSYNC
96	SDMMC1_CLK	VI_PCLK
97	SDMMC1_DAT3	VI_D5
98	SDMMC1_CMD	VI_D1
101	SDMMC1_DAT0	VI_D2
103	SDMMC1_DAT1	VI_D3

**Software****Customer Software**

We request customers to check their own software in detail to guarantee functionality on the new product version. For example, please check that no excessive warning or error logging is done in the background which might compromise system performance or flash storage lifetime.

Without the level shifter being assembled, the following Tegra pins are floating:

Tegra Pin	X1 Pin#
VI_D0	71
VI_D1	98
VI_D2	101
VI_D3	103
VI_D4	79
VI_D5	97
VI_D6	67
VI_D7	59
VI_D8	85
VI_D9	65
VI_D10	69
VI_D11	77
VI_HSYNC	94
VI_PCLK	96
VI_VSYNC	81

**Toradex Linux BSP**

- The removal of the TI 74AVCA164245ZQLR does not impact the functionality of software, i.e. no errors are displayed
- Coming out of Reset, some of these pins will have the internal pull-up/down enabled (for more details see Section 4.4 - List Functions in [Colibri T30 datasheet](#))
- After boot, If not handled properly, the affected Tegra pins listed above will be left floating as a direct consequence of removing the TI 74AVCA164245ZQLR level shifter. Thus, Toradex strongly recommends enabling the pull-down resistor on these Tegra pins (see related [developer website guide](#))

**Windows CE**

- The removal of the TI 74AVCA164245ZQLR do not impact the functionality of software, i.e. no errors are displayed. All the pins are left on pull-down unless the camera interface is effectively used

## 5. Contact

---

- Please contact Toradex if you have any questions
- For commercial and sales questions, please contact [shop@toradex.com](mailto:shop@toradex.com)
- For technical questions, please contact [support@toradex.com](mailto:support@toradex.com)