

# Product Change Notification (PCN): 0037 Apalis iMX8QM 4GB WB IT V1.1E and 0047 Apalis iMX8QM 4GB IT V1.1D

Date of publication: 02 May 2024

Update #1 on 07 May 2024: The Hardware section on “Customer Impact” has been updated.

## Table of Contents

- 1. Affected Products
- 2. Product Phase-in / Phase-out Schedule
- 3. Description of Changes
  - Change #1: SoC change
  - Change #2: RAM Change
  - Change #3: R51 assembly state from assembled to not assembled
  - Change #4: Edge Connector Chamfering
  - Change #5: Ethernet clock source change
- 4. Customer Impact
  - Hardware
  - Software
    - Torizon OS
    - Toradex Embedded Linux BSP
- 5. Contact

## 1. Affected Products

End of Life Product		Replacement Product	
Part Number	Product Name	Part Number	Product Name
00371104	Apalis iMX8QM 4GB WB IT V1.1E	00371105	Apalis iMX8QM 4GB WB IT V1.1F
00471103	Apalis iMX8QM 4GB IT V1.1D	00471104	Apalis iMX8QM 4GB IT V1.1E

## 2. Product Phase-in / Phase-out Schedule

End of Life Product		Replacement Product	
Part Number	Estimated Schedule	Part Number	Estimated Schedule
00371104	Last time buy (LTB): 2024-10-13	00371105	Samples: July/2024
00471103	Last time ship (LTS): 2025-04-11	00471104	

### 3. Description of Changes

---

#### Change #1: SoC change

- SoC part number has changed from NXP MIMX8QM6AVUFFAB to NXP MIMX8QM5AVUFFAB

#### Change #2: RAM Change

- RAM part number has changed from Micron MT53D512M32D2DS-046 IT:D to Micron MT53E512M32D1ZW-046 IT:B

#### Change #3: R51 assembly state from assembled to not assembled

- Strapping of the KSZ9131 Ethernet PHY changed from “1111” (which is reserved on KSZ9131) to “1110”

#### Change #4: Edge Connector Chamfering

- The PCB edge connector changed from non-chamfered to chamfered

#### Change #5: Ethernet clock source change

- OSC4 has changed from MEMS to crystal-based type

### 4. Customer Impact

---

#### Hardware

- The change of the clock source of the on-SoM Ethernet PHY from a MEMS oscillator to a crystal-based device results in lower jitter and addresses the potential Ethernet compliance issue from HAR-10131: <https://developer-archives.toradex.com/apalis-imx8-issue-tracker?key=HAR-10131#tab-errataknown-issues> .
- Software support has never been added for the HiFi 4 DSP IP featured in the SoC. By changing to a different SoC part number, the hardware DSP feature is removed accordingly. There's no impact on other IPs and characteristics of the SoC.
- No other impact is expected, however, please carefully verify the new product version in your environment.

## Software

### Torizon OS

- No impact is expected due to the changes mentioned above.

### Toradex Embedded Linux BSP

- No impact is expected due to the changes mentioned above.

## 5. Contact

---

- Please contact Toradex if you have any questions.
- For commercial and sales questions, please contact [shop@toradex.com](mailto:shop@toradex.com)
- For technical questions, please contact [support@toradex.com](mailto:support@toradex.com)