

# Product Change Notification (PCN)

Transition from

Viola Plus V1.2A to Viola Plus V1.2B

Date of Publication: 2017-07-10

## 1. Toradex Product Numbers Affected

EOL Product		Replacement Product	
Part Number	Product Name	Part Number	Product Name
01421200	Viola Plus V1.2A	01421201	Viola Plus V1.2B

## 2. Product Phase in / Phase out Schedule

EOL Product		Replacement Product	
Part Number	Estimated Schedule	Part Number	Estimated Schedule
01421200	Product will be sold until inventory is depleted.	01421201	Volume Production: July 2017

## 3. Description of Changes

From 01421200 Viola Plus V1.2A to 01421201 Viola Plus V1.2B:

- The terminal of the battery holder on Viola Plus V1.2A could lead to an open connection between the battery and the respective ground pad on the PCB. More details are available in the respective errata document under Errata #1:  
<https://docs.toradex.com/103840-viola-carrier-board-errata.pdf>  
The problem is fixed on V1.2B by changing the paste mask of the ground pad.

## 4. Customer Impact

### 4.1. Hardware Design

- The change solves Errata #1 mentioned above but doesn't have any other impact on hardware.

### 4.2. Software

- This change doesn't have any impact on software.

## 5. Contact

---

Please contact Toradex if you have any questions.

For commercial and sales questions please contact [shop@toradex.com](mailto:shop@toradex.com)

For technical questions please contact [support@toradex.com](mailto:support@toradex.com)